

Line	Description	Qty	Unit
1	Screw, Cap, Hex Head, 1/4in-20 UNC, 2in, Carbon Steel, Gr.5, ASA B18.6.2	500	EA
2	Screw, Cap, Hex Head, 1/4in-20 UNC, 1-1/4in, Carbon Steel, Gr.5, ASA B18.6.2	500	EA
3	Screw, Cap, Hex Head, 3/8in-16 UNC, 3in, Carbon Steel, Gr.5, ASA B18.6.2	500	EA
4	Screw, Cap, Hex Head, 3/8in-16 UNC, 5in, Steel	500	EA
5	Bolt, Hex Head, 3/4in-16 UNF, 1-1/2in, Carbon Steel, Gr.5, ASA B18.6.2	500	EA
6	Bolt, Machine, Hex Head, 1/2in-13 UNC, 3in, Carbon Steel ASTM A307 + Nut	500	EA
7	Bolt, Machine, Hex Head, 1/2in-13 UNC, 2-1/2in, Carbon Steel ASTM A307 + Nut	500	EA
8	Bolt, Machine, 1/2in x 2-1/4in, Steel, w/ Hex Nut	500	EA
9	Bolt, Machine, Hex Head, 1/2in-13 UNC, 5in, Carbon Steel ASTM A307 + Nut	500	EA
10	Bolt, Machine, 1/2in x 3-1/2in, Steel, w/ Hex Nut	500	EA
11	Bolt, Hex Head, 1/4in x 3-1/2in, Steel, w/ Nut	500	EA
12	Bolt, Machine, Hex Head, 5/16in-18 UNC, 1-3/4in, ASTM A307 + Nut	500	EA
13	Bolt, Hex Head, 5/16in x 4in, Steel, w/ Hex Nut	500	EA
14	Bolt, Machine, Hex Head, 5/16in-18 UNC, 1-1/2in, ASTM A307 + Nut	500	EA
15	Bolt, Machine, Hex Head, 5/16in-18 UNC, 2in, ASTM A307 + Nut	500	EA
16	Bolt, Machine, Hex Head, 1/4in-20 UNC, 3in, ASTM A307 + Nut	500	EA
17	Bolt, Machine, Hex Head, 5/16in-18 UNC, 1/2in, ASTM A307 + Nut	500	EA
18	Bolt, Machine, 1/4in x 4in, Steel, w/ Hex Nut	500	EA
19	Washer, Lock, 3/16in ID x 0.047in, Spring Steel, Medium Helical	500	EA
20	Washer, Lock, 1/4in ID x 0.062in, Spring Steel, Medium Helical	500	EA
21	Washer, Spring Lock, for 5/8in Bolt, Steel	500	EA